



Sg. Kelian, Penang

This photo shows the condition before EM was applied. The sludge accumulation was estimated as deep as 1 m.



This photo shows the condition after EM was applied. 3 months later entire sludge and foul odour completely disappeared.

